

FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT

X=SHOP, V=VENDOR, O=OTHER

MONTH

MARCH 2018

| Equip # | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | Equip # | COMMENTS: |
|---------|---|---|---|---|---|---|---|---|---|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|---------|---|
| A4305 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | A4305 | |
| A16 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | A16 | |
| C4300 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | C4300 | |
| D4301 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | D4301 | |
| D4305 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | D4305 | |
| B4315 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | B4315 | |
| B4318 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | B4318 | |
| BR74 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | BR74 | |
| BR75 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | BR75 | |
| BR77 | | | | | | | | | | | | | | | | | | | | | X | | | | | | | | | | | BR77 | Replaced p-side door handle assembly and 12 v air solenoid for air horn. |
| BR94 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | BR94 | |
| BS82 | | | | | | | | | | | | | | | | | X | | | | | | | | | | | | | | | BS82 | R&R engine light, order parts for engine coolant temperature. |
| Engine6 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | Engine6 | |
| E282 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E282 | |
| E288 | | | | | | | X | | | | | | | | | | | | | | | | | | | | | | X | | | E288 | R&R wheel turn signal light module assembly: Replaced pressure relief valve on wet tank. |
| E294 | | | | | | | | | | X | | | | | | | | | | | | | | | | | | | | | | E294 | Rebuilt r-rear discharge and tank filler: Replaced broken bolts that support the 10' 3" pipe. |
| E295 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E295 | |
| E71 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E71 | |
| E72 | | | | | | | | | | | | | | | | | | | | | X | | | | | | | | | | | E72 | Performed 90 day compliance: Cross rotated front steer tires. |
| E73 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E73 | |

