

FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT
X=SHOP, V=VENDOR, O=OTHER

MONTH

MARCH

Equip #	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Equip #	COMMENTS:
A16																																A16	
BR74																																BR74	
BR75																																BR75	
BR77																	4															BR77	Perform A service. R&R tank level sensor, foam pump control head, windshield washer pass through and cab door seals.
BR94																															BR94		
BS82																															BS82		
B4315																															B4315		
B4316									2												2										B4316	B Service. Removed stripped center console machine screws. Replaced Kenwood radio head. Performed radio check.	
B4318																															B4318		
C4300																															C4300		
D4301																															D4301		
D4305																															D4305		
DT43 (old)																													1	DT43 (old)	R&R Fuel Cooler		
Engine 6																														Engine 6			
E282																															E282		
E288								2													3										E288	R&R U joint at gear box input yoke. Adjusted rear brakes. Greased engine and performed A service. Recharged A/C. Repaired wiring on code 3 light in the grill.	
E294	4		3																											E294	R&R bad U joint at PTO gear box. B Service		
E295								11																							E295	Diagnose multiple code 3 lights not working. B Service. R&R kusssmaul indicator. R&R high water temp buzzer/light combo on pump panel. 90 day compliance. Replaced 30 amp ATC fuse. R&R connector to top right rear code 3 light.	
E71																														E71			
E72									4					2															2	E72	Replaced missing "U" bolt mounting nuts for electronic aux pump throttle actuator. Replaced both 2" amber reflector on both sides of the cab. B Service. Replaced air dryer filter, purge valve, turbo valve, pump panel water level sight tube. Recharged A/C system. Performed manual regen. Removed aux pump electronic throttle actuator for welding repair. Welded broken aux pump motor throttle. Reinstalled		
E73									3					5																E73			
E74																														E74			
E75																														E75			

