

FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT

X=SHOP, V=VENDOR, O=OTHER

MONTH

FEBRUARY

Equip #	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Equip #	COMMENTS:
A06																																A06	
BR74																																BR74	
BR75																																BR75	
BR77					X	X																										BR77	Replaced all 4 U joints on steering; R&R tank full valve & O-rings on #1 2 1/2" and rear 2 1/2" discharge drain valve; R&R oil leak in front engine.
BR94																											X					BR94	90 day compliance: Replaced windshield washer knob.
BS82																												X				BS82	Replaced passenger side rear view mirror marker light; Performed 90 day compliance.
B4315															X																	B4315	Performed B-service: R&R front and rear tires.
B4318																																B4318	
C4300																																C4300	
D4301																																D4301	
D4305																																D4305	
Engine 6																																Engine 6	
E262																											X					E262	R&R passengar side inside dual for flat tire.
E288																	X															E288	R&R passenger side rear wheel seal; Performed A-service.
E294																		X														E294	Rebuilt aux pump; R&R both headlights-low beams; R&R 2 light bulbs on pump panel.
E295																											X					E295	R&R driver front wheelseal; R&R both front axle oil hubs and both front brakes and drums; Performed 90 day compliance.
E71																											X					E71	Performed 90 day compliance.
E72																											X					E72	Performed 90 day compliance.
E73																		X	X								X					E73	Performed 90 day compliance; R&R E-6 brake valve; Repaired connections on cab controller; Installed kusmal charger and auto eject.
E74																																E74	
E75																											X					E75	Performed 90 day compliance.
E77																												X				E77	Performed 90 day compliance; R&R alternator with 14 volt, 270 amp; R&R purge and turbo valves.
E82																											X	X				E82	Replaced bent exhaust tip and tightened a loose mounting bracket; Performed B-service; R&R coolant leak.
E83									X						X					X							X					E83	Performed 90 day compliance; R&R door latch with new one; R&R pump engage shifter handle; Replaced front shocks; R&R starter.
E84									X																							E84	Replaced 2 bad marker/turn LED's on steps on driver side pump panel.

