

**FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT**  
**X=SHOP, V=VENDOR, O=OTHER**

**MONTH**  
**APRIL 2018**

Equip #	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Equip #	COMMENTS:
A16																																A16	
BR74																																BR74	
BR75																																BR75	
BR77																																BR77	
BR94																																BR94	
BS82																																BS82	Performed A, B-service: R&R suspension, steering & drive line compartm
B4315													X																			B4315	Sent to Sequoia Chevrolet for B-service.
B4318																																B4318	
C4300																										X						C4300	Performed C-service: Replace spark plugs and performed safety inspection
D4301																																D4301	Replaced ignition key tumbler.
D4305																										X						D4305	Replaced ignition key tumbler.
Engine 6																																Engine 6	
E282																																E282	
E288																																E288	
E294																																E294	
E295																																E295	
E71						X																										E71	Replaced all four rear drive tires: Replaced one code 3 light bulb.
E72																							X									E72	Replaced front bumper hose swivel: Replaced A/C condenser fan relay.
E73																																E73	
E74																																E74	
E75																																E75	
E77		X																														E77	Performed C-service: Replaced aux engine oil and filters.
E82																																E82	
E83							X																									E83	R&R front seen lights w/new LEG lights.
E84																																E84	
E85																																E85	
E86			X							X						X																E86	Replaced fog light and cover: B-service: Replaced compartment door latch



**FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT**  
**X=SHOP, V=VENDOR, O=OTHER**

<b>T4328</b>						X																									<b>T4328</b>	Replaced side ladder mounting bracket.
<b>U-10</b>						X																									<b>U-10</b>	Replaced side ladder mounting bracket.
<b>U-11</b>																															<b>U-11</b>	
<b>U-17</b>						X																									<b>U-17</b>	Replaced side ladder mounting bracket.
<b>U-18</b>																															<b>U-18</b>	
<b>U-19</b>						X																									<b>U-19</b>	Replaced side ladder mounting bracket.
<b>U4348</b>																															<b>U4348</b>	
<b>U-30</b>						X																									<b>U-30</b>	Replaced side ladder mounting bracket.
<b>WT72</b>																															<b>WT72</b>	
<b>WT82</b>						X																									<b>WT82</b>	Replaced side ladder mounting bracket.
<b>WT83</b>																															<b>WT83</b>	
<b>WT86</b>																															<b>WT86</b>	
<b>WT90</b>																															<b>WT90</b>	
<b>WT93</b>																															<b>WT93</b>	
<b>WT96</b>																															<b>WT96</b>	