

FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT
X=SHOP, V=VENDOR, O=OTHER

MONTH
JULY

| Equip # | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | Equip # | COMMENTS: |
|----------|---|---|---|---|---|---|---|---|---|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----------|--|
| A09 | | | | | | | | | | | | | | | | | | | | | | | | | | | X | | | | | A09 | B-service: R&R water pump, fan belt, right & left upper A arms: R&R all |
| BR73 | | | | | | | | | | | | | | | X | | | | | | | | | | | | X | | | | | BR73 | Changed alternator for not charging: Replaced bad batteries: R&R turn signal flasher. |
| BR74 | X | | | | | | | | | | | | | | X | | | | | | | | | | | | | | | | | BR74 | Performed C-service: R&R main engine oil filter: Rebuilt tank to pump Elkhart valve:R&R radiator for overheating: Replaced brake foot valve. |
| BR75 | | | | | | | | | | | | | | | X | | | | | | | | | | | | | | | | | BR75 | R&R radiator for overheating. |
| BR77 | | | | | | | | | | | | | | | | | | | X | | | | | | | | | | | | | BR77 | Replaced p-side rear brake drum. |
| BS82 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | BS82 | |
| B4315 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | B4315 | |
| B4318 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | B4318 | |
| C4300 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | C4300 | |
| D4301 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | D4301 | |
| D4305 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | D4305 | |
| Engine 6 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | Engine 6 | |
| E282 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E282 | |
| E288 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E288 | |
| E294 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E294 | |
| E295 | | X | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E295 | Replaced brake foot valve assembly: R&R 6 foot valve plastic housing. |
| E71 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E71 | |
| E72 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E72 | |
| E73 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E73 | |
| E74 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E74 | |
| E75 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E75 | |
| E77 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E77 | |
| E82 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E82 | |
| E83 | | | | | | | | | | | | | | | | | | | | | | | | X | | | | | | | | E83 | R&R main engine high pressure fuel pump assembly: Replaced main radiator surge tank due to coolant leak: Performed Main and Aux pump |
| E84 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E84 | |
| E85 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E85 | |
| E86 | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | | E86 | |

