

FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT

X=SHOP, V=VENDOR, O=OTHER

MONTH

DECEMBER 20

Equip #	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Equip #	COMMENTS:
A16																																A16	
BR73																												X				BR73	90 day compliance.
BR74																											X					BR74	90 day compliance.
BR75																										X						BR75	90 day compliance.
BR77																										X						BR77	90 day compliance.
BR94																										X						BR94	90 day compliance.
BS82																																BS82	
B4315									X																							B4315	Replaced aux battery on driver side.
B4316																					X											B4316	B-service: Replaced oil & air filter and window wipers: Replaced all 4 tires & TPS sensors: Installed new spare tire.
B4317														X																		B4317	Stripped out rear slide: Removed kussmal box from bed of truck: Made new mount for camper shell intercom work light toggle switch.
B4318																																B4318	
C4300																																C4300	
D4301																																D4301	
D4305																																D4305	
Engine 6																															Engine 6		
E282																																E282	
E288																			X									X				E288	90 day compliance: R&R all 3 vehicle batteries: R&R kussmal auto charge
E294												X															X					E294	90 day compliance: R&R both driver rear fan and tool compartment door latches: R&R both p and d-side BA & medical compartment lift supports.
E295																			X									X				E295	90 day compliance: Rebuilt both primer valves: Replaced 1/4" pump pane
E71																											X					E71	90 day compliance.
E72																											X					E72	90 day compliance.
E73																											X					E73	90 day compliance.
E74																																E74	
E75																										X						E75	90 day compliance.
E77																										X		X				E77	90 day compliance: R&R dash computer, L1 door sensor not working.
E82												X																X				E82	90 day compliance: Replaced rear brake shoes, spring kits, brake drums and all 4 drive tires.

