

**FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT**  
**X=SHOP, V=VENDOR, O=OTHER**

**MONTH**  
**JANUARAY**

Equip #	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Equip #	COMMENTS:
A06																																A06	Performed B-service: Replaced oil and filter, air and fuel filter, wiper blades: Replaced all four tires and mounted and balanced.
BR74																																BR74	
BR75																																BR75	
BR77																																BR77	
BR94																																BR94	
BS82																									X							BS82	R&R engine: Replaced diesel oxidation catalyst, high pressure fuel pump, engine oil cooler and resealed center valley plate gasket.
B4315																	X															B4315	Sent to Sunnyside Auto to complete B-service.
B4316	X																															B4316	R&R both hand mic's and flash light charging base: Fabricated mounting bracket for HT charger.
B4317														X																		B4317	New install all code 3 lighting, siren, radio, command box in rear, tough book in rear touch screen in front, radio antennas and tracker.
C4300																																C4300	
D4301																																D4301	
D4305																																D4305	
Engine 6																																Engine 6	
E282																																E282	
E288																																E288	
E294																																E294	
E295																																E295	
E71																																E71	
E72																	X															E72	Replaced missing magnetic exhaust tip assembly and 5" to 4" exhaust pipe reducer with clamps.
E73																																E73	
E74																																E74	
E75																																E75	
E77																																E77	
E82																																E82	
E83																																E83	
E84						X			X																					X		E84	Replaced missing knob on #2 discharge handle: R&R bad plug on cord reel to kusmal port: Replaced d-side low beam headlight.



