

FRESNO COUNTY FIRE PROTECTION DISTRICT MONTHLY SHOP REPORT

X=SHOP, V=VENDOR, O=OTHER

MONTH

FEBRUARY

Equip #	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Equip #	COMMENTS:
A06																				X												A06	R&R 20 amp mini fuse for OBDII communication plug: Replaced all spark plugs, plug wires, serpentine belt, belt tensioner and idler pulley.
BR74																																BR74	
BR75																																BR75	
BR77																			X								X					BR77	R&R all engine coolant hoses: Replaced aux pump gear box and air dryer assembly: R&R reverse beeper, trans & voltage gauges.
BR94																																BR94	
BS82																																BS82	
B4316																			X									X				B4316	R&R seat cushions on driver seat: R&R both headlights: Repaired wiring for camper shell lights: R&R brake light switch: R&R left turn signal.
B4318																																B4318	
C4300																																C4300	
D4301														X																		D4301	Performed B-service: Rotated and balanced all 4 tires: Replaced both front hub bearing assemblies: Replaced wiper blades.
D4305																																D4305	
Engine 6																																Engine 6	
E282																																E282	
E288																												X				E288	R&R 12 volt primer motor, disassembled primer pump: Tighten driver side pump panel machine screws.
E294																																E294	
E295									X								X								X							E295	R&R all fluid levels, tires and headlight/running lights: Replaced 1 red LED marker light: R&R all 4 rear tires: Performed B-service.
E71																X												X			E71	R&R window regulator on driver side: Replaced primer motor ball switch	
E72																																E72	
E73																																E73	
E74																																E74	
E75																																E75	
E77																																E77	
E82																																E82	
E83																											X					E83	Performed B-service: R&R cold side charge air pipe.
E84																						X				X						E84	Resilcone/resealed both front & passenger doors: Adjusted both front door strikers: Performed B-service: R&R oil leak at head gasket.
E85																																E85	

